


STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/95 To (mo./yr.) 12/95
2. DOGM File Number (Mine No): M 10431004
3. Mine Name: Utelite
4. Mineral(s) Mined (or permitted to mine): Mancos Shale
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
N 1/2 NW 1/4, Section 8, Township 15, Range 5E  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_ Township \_\_\_\_ Range \_\_\_\_  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_ Township \_\_\_\_ Range \_\_\_\_
7. Name of Operator or Company: Utelite Corporation
8. Permanent Street Address: 3 1/2 miles S. Wanship, Hwy 32  
City, State, Zip: Coalville, Utah 84017  
Phone: 801-359-8541
9. Company Representative (or designated operator):  
Name: Carsten N. Mortensen  
Title: President  
Business Address: PO Box 387  
City, State, Zip: Coalville Utah 84017  
Phone: 801-359-8541  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 210,000 tons



3. How much additional acreage was disturbed during the past year? none
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.  
All mining was done in the existing quarry.
5. How much acreage was reclaimed during the past year? none.
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
There was no work done on reclamation although natural regrowth has continued.
7. What is the total disturbed acreage at years end? 30
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
The mining for 1996 should all continue in the existing quarry.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Title of Operator:

Signature of Operator:

Date:

Carsten W. Mortensen  
President  
Carsten W. Mortensen  
1-23-96